

IN THE SPECIFICATION:

Page 6, the paragraph beginning at line 1 is corrected as follows:

The raised surface 36 has a plurality of mounting holes 41. The lower surface 38 has door panel pivot holes 43 and ~~[[44]]~~ 43A in outwardly extending ends 102 and 103 of lower surface 38.